

Project: Floating crude-oil tank roof
Location: Fawley, west of Southampton, England
Completed: September 2007
Specification: Zinga 120-140µm



Roof-top showing corroded paintwork



View of roof showing spent blast-media




Close-up view showing true size



Aerial view showing blasted areas

Project Study

Project: Floating crude-oil tank roof
Location: Exxon Mobil, Fawley, west of Southampton, England
Completed: September 2007
Specification: Zinga 120-140µm



Problem: The crude-oil floating tank-roof was corroded. The tank farm is adjacent to the sea and the contracting team had previously had problems when applying epoxy coatings. Their blast hoses were dragging across the wet epoxy which was surface dried but was still soft underneath.

Solution: Blast-clean the entire surface and apply Zinga to a thickness range of 120 - 140µm DFT.

The work was carried out by Cape Industrial Services
Contracts manager: Steve Blight
Telephone number: 02380-892745

For more information on this project or for more details on the sales and distribution of Zinga and its related products within this region, please telephone Christine Garner from MG Duff on telephone number 01243-533336.